

Oil Field Environmental Incident Summary

Incident: 20150819153641

Date/Time of Notice: 08/19/2015 15:36

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: Schmitz 4-9H

Field Name: PAINTED WOODS

Well File #: 21991

Date Incident: 8/16/2015

Time Incident: 08:00

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 102

Sec: 4

Qtr: LO T3

Location Description: From Williston, Hwy 85 South, Turn West on 42nd St NW, 3.6 miles to access road turn South, 0.8 miles turn right

Submitted By: Dustin Anderson

Received By:

Contact Person: Dustin Anderson
6205 16th Ave. W.
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident Stuffing Box Leak

Release Contained in Dike No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Barrels	20	Barrels	20	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/19/2015

Clean Up Concluded: 8/17/2015

Risk Evaluation:

Low

Areal Extent:

Not determined

Potential Environmental Impacts:

None

Action Taken or Planned:

Replaced gasket

Wastes Disposal Location: Indian Hills

Agencies Involved:

Updates

Date: 8/19/2015 **Status:** Reviewed; Followup Required **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 8/20/2015 **Status:** Inspected; More Followup Required **Author:** Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 15:00. 86 degrees, wind SW at 10, clear. Well pad clean and well kept. New gravel in place. Inspected perimeter. Oil spray left pad on east side. Area 75 meters by 25 meters has been clipped, and vegetation has been removed. Area outside of pad boundary (native grass pasture) also has been sprayed and not clipped. Zone of impact easily seen with the naked eye and confirmed with tissue wipe. Area not remediated is 77 paces wide narrowing down to a point 95 paces to the east, then hooking south around the hill side to form a wide horn shape. GPS coordinates and pictures collected. All visual evidence indicates the vegetation captured all or nearly all of the spray. Off site 15:50.